



Worldwide repairs carried out with PolymerMetal[®]

REP-# 119



Repair of the anti-wear blinding, carried out in a steel mill using MM-metal SS-steelceramic and Hardener yellow.

MultiMetall
the MetalExistenceCompany[®]